


COPY

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau 42-K358.3.
Approval expires 12-31-55.

Land Office Las Cruces
Lease No. 055546
Unit _____



SUNDRY NOTICES AND REPORTS ON WELLS

| | | |
|--|--|-------------------------------------|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF | <input checked="" type="checkbox"/> |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING | |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING | |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR | |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT | |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY | |
| NOTICE OF INTENTION TO ABANDON WELL | | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 29, 19 56

Well No. 4 is located 1980 ft. from N line and 1980 ft. from E line of sec. 5

SE 1/4 NW 1/4 25 S 37 E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Langlie Mattix Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 296' from 0' of 8 5/8" casing. Cemented with 325 sacks cement.
Circulated to surface. Plugged down 5:30 A.M. 3-28-56. Waited 24 hours.
Pressured up with 600# for 30 min. No leaks.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company R. Olsen Drawer #2, Jal, New Mexico
Address 2811 Liberty Bank Bldg.
Okla. City, Okla.
By _____
Title _____