

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<p><b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p>
<p>OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/></p>		<p>5. State Oil &amp; Gas Lease No. -----</p>
<p>6. Name of Operator <b>Skelly Oil Company</b></p>		<p>7. Unit Agreement Name -----</p>
<p>8. Address of Operator <b>P. O. Box 1351, Midland, Texas 79701</b></p>		<p>8. Farm or Lease Name <b>J. W. Sherrell</b></p>
<p>9. Location of Well UNIT LETTER <b>B</b> <b>330</b> FEET FROM THE <b>North</b> LINE AND <b>1650</b> FEET FROM <b>East</b> <b>6</b> <b>25S</b> <b>37E</b> LINE, SECTION TOWNSHIP RANGE NMPM.</p>		<p>9. Well No. <b>3</b></p>
<p>10. Field and Pool, or Wildcat <b>Jalmat (Yates)</b></p>		<p>10. Field and Pool, or Wildcat <b>Jalmat (Yates)</b></p>
<p>11. Elevation (Show whether DF, RT, GR, etc.) <b>3238' DF</b></p>		<p>12. County <b>Lea</b></p>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
<p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <b>P &amp; A Jalmat Gas and repair casing leak</b> <input checked="" type="checkbox"/></p>	<p>PLUG AND ABANDON <input type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>REMEDIAL WORK <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOB <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p> <p>ALTERING CASING <input type="checkbox"/></p> <p>PLUG AND ABANDONMENT <input type="checkbox"/></p>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well had been producing as a Skelly Jalmat (Yates) Gas well and as an injection well in the Langlie-Mattix Oil Zone as Union Texas Petroleum's Langlie Jal Unit Well No. 33. Both zones were shut in July 25, 1972, due to an apparent casing leak; and we propose plugging the Jalmat Gas Zone, repairing the casing leak and returning the Langlie-Mattix Zone to Union Texas as follows:

- 1) Rig up pulling unit and pull downhole equipment.
- 2) Repair hole in surface casing immediately below bradenhead.
- 3) Run packer and set bridge plug at 3075'. Spot sand on top of bridge plug and set packer at 2700'.
- 4) Squeeze Jalmat Gas Zone perfs. 2830-3055' with 300 sacks of expanding cement, limiting squeeze pressure to less than 1000# to prevent communication with oil zone below. Pull packer.
- 5) Drill out cement and clean out to top of bridge plug. Test casing to 500#. Retrieve bridge plug.
- 6) Rerun downhole equipment and turn over operation of well to Union Texas Petroleum.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED (signature) W. R. Crow TITLE Lead Clerk DATE Oct. 7, 1972

APPROVED BY Orig. Signed by Joe D. Ramey Dist. I, Supv. TITLE  DATE OCT 10 1972

CONDITIONS OF APPROVAL, IF ANY: