

DUPLICATE

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

RECEIVED

NOV 5 1953

MISCELLANEOUS REPORTS ON WELLS
OIL CONSERVATION COMMISSION

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETION OPERATION		REPORT ON (Other) Dual Completion	X

10-21-53
(Date)Dallas, Texas
(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

Dalport Oil Corporation
(Company or Operator)W. H. Harrison
(Lease)Algerita Drilling Company
(Contractor)

Well No. 1 in the SW 1/4 NE 1/4 of Sec. 7

T. 25S, R. 37E, NMPM, Jalco Gas Pool, Lea County.

The Dates of this work were as follows: 10-14-53

Notice of intention to do the work (was) (was not) submitted on Form C-102 on _____, 19____, (Cross out incorrect words)

and approval of the proposed plan (was) (was not) obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Dual Completion - New Mexico Oil Conservation Commission Order DC-10, dated September 28, 1953. Perforated Yates Gas Section from 2820 to 2900 and 2952 to 2976 with 2 jet shots per foot. Fractured with 3000 gallons Western Fracture-jel. Set Guiberson L-30 Packer with hold down at 3167'.

Witnessed by George G. Todd
(Name)Dalport Oil Corporation
(Company)Superintendent
(Title)

Approved:

OIL CONSERVATION COMMISSION

Engineer District 1

NOV 6 1953
(Date)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name _____
Vice-PresidentPosition _____
DALPORT OIL CORPORATIONRepresenting _____
Address 930 Fidelity Union Life Bldg. Dallas, Tex

DIAGRAM OF MECHANICAL COMPLETION
 OF LPORT OIL CORPORATION'S WM. H. ARRISON
 SW NE Section 7, T25S, R37E
 LEA COUNTY, NEW MEXICO.

