

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS
(Submit to appropriate District Office as per Commission Rule 1106)

Company Dalport Oil Corporation, 930 Fidelity Union Life Bldg, Dallas, Texas
(Address)

Lease F. C. Winters "A" Well No. 4 Unit K S 7 T 25-S R 37-E

Date work performed 6-12-55 POOL Cooper - Jal

This is a Report of (Check appropriate block) ☒ Result of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

3268' 5" C. D. 11" Lone Star P.W.

Casing cemented with 200 sacks

Tested casing with 1000 psi

Tested C.D.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl. Date _____

Tbng. Dia. _____ Tbng. Depth _____ Oil String Dia _____ Oil String Depth _____

Perf. Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER

	BEFORE	AFTER
Date of Test		
Oil Production, bbls. per day		
Gas Production, Mcf per day		
Water Production, bbls. per day		
Gas-Oil Ratio, cu. ft. per bbl.		
Gas Well Potential, Mcf per day		
Witnessed by _____		

		(Company)
Name	Oil Conservation Commission	I hereby certify that the information given above is true and complete to the best of my knowledge.
Title		Name <u>W. E. Tedder</u>
Date		Position <u>Vice - President</u>
		Company <u>Dalport Oil Corporation</u>