

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

HOBBS OFFICE OCC

MISCELLANEOUS REPORTS ON WELLS

1954 APR 27 PM 2:37

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF	<input checked="" type="checkbox"/>	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETION OPERATION		REPORT ON (Other)	

4-26-54

(Date)

Dallas, Texas

(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

Dalport Oil Corporation

(Company or Operator)

E. C. Winters "C"

(Lease)

Frost & Porter Drilling Co

(Contractor)

Well No. 4 in the NE 1/4 SE 1/4 of Sec. 7

T. 25S, R. 37E, NMPM, Langlie-Mattix Pool, County.

The Dates of this work were as follows:

Notice of intention to do the work (was) (was not) submitted on Form C-102 on 4-23-54, 19, (Cross out incorrect words)

and approval of the proposed plan (was) (was not) obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Cemented 3225' - 7" O. D. 20# J-55 Seamless casing with 400 sacks - Two Staged.

Tested with 1000# before and after drilling plugs. Tested O. K.

Witnessed by George G. Todd
(Name)

Dalport Oil Corporation
(Company)

Superintendent
(Title)

Approved: OIL CONSERVATION COMMISSION

D. G. Stanley
(Name)
(Title)
(Date)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name *E. C. Winters*
Position Vice-President

Representing Dalport Oil Corporation
Address 930 Fidelity Union Life Bldg. Dallas, Tex