

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

U. S. Land Office **Las Cruces**
Lease or permit No. **032511-D**
Langlie - Jan 31

Allottee
Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	2
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. **1** is located **660** ft. from **N** line and **360** ft. from **E** line of sec. **8-35-37**
C NE 1/4 8 (1/4 Sec. and Sec. No.) **25G** (Twp.) **37E** (Range) **121M** (Meridian)
Langlie (Field) **Lee County** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is **3205** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well drilled to 3290'. 7" OD - 24# API Grade B Seamless Casing was cemented at 3284' with 360 lbs common cement. Casing and surface fittings were tested 10-20-37 with 1100' pressure. Pressure decreased 20# in 30 minutes. Cement plug was drilled out 10-21-37 and casing tested with 1200' pressure. Pressure decreased 30# in 30 minutes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Garmon-Richard Oil Corporation**
Address **Box 1097, Hobbs, N.M.**

By **Winston E. [Signature]**
Title **Manager**