

Indian Agency.....

(SUBMIT IN TRIPLICATE)

Land Office.....

Lease or permit No.....

Jol #1

032311-D

Allottee.....

Lease No.....

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Section 8, 19 37

Well No. 1 is located 640 ft. from [N] line and 664 ft. from [E] line of sec. 8-25-37

C NE NE 8
(14 Sec. and Sec. No.)333
(Twp.)37E
(Range)111W
(Meridian)Lorelie
(Field)Lee County
(County or Subdivision)New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 3203 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well drilled to total depth 1252'. 2-5/8" casing (36" API Gd. C
tubs.) cemented at 1808' with 500 lbs. cement was tested with 1100' pressure before drilling plug. Pressure decreased 30' in 30 min.
after drilling out cement plug casing was again tested with 1100' pressure. Pressure decreased 50' in 30 minutes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Anderson-Richards Oil Corporation

Address Box 1697, Hobbs, New Mexico

By Weston Payne
Title Asst. Mgr.