

(SUBMIT IN TRIPLICATE)

U. S. Land Office Las Cruces

Allottee.....

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Lease or permit No. 32511-0

L. J. Langle  
301 227-1

Lease No.....

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

....., 1937

Well No. 1 is located 120 ft. from N line and 600 ft. from E line of sec. 8-25-77

Q. N. NE 8 (1/4 Sec. and Sec. No.) 25 (Twp.) 37E (Range) 1-2 (Meridian)

Langle (Field) Lee County (County or Subdivision) N. M. (State or Territory)

The elevation of the derrick floor above sea level is ..... ft. 120 ft. is later

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well drilled to total depth of 1252' in salt. Had top of salt (driller's log) at 1220'. 9-5/8" - 35# oil pipe & cementless casing cemented at 1206' with 500 lbs. of cement. Partials to test casing and cement to a depth of 10-1-37.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Indep. Oil & Gas Co.

Address Box 1-7,

Hobbs, N. M.

By W. L. Payne

Title Asst. Geol.

