

(SUBMIT IN TRIPLICATE)

U. S. Land Office Las Cruces

Lease or permit No. 032511-E

Allottee.....

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

A. J. Langlie

Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	☒
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

11-9, 1937

Well No. 1937 1 is located 1980 ft. from [N] line and 660 ft. from [E] line of sec. 8-25-37

Q. 12 NE Section 8 25S 37E 10N
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Langlie Lea County New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3181 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

9-5/8" OD - 26# Seamless Casing cemented at 1181 with 500 sacks cement was tested 11-4-37 with 1200' pressure before drilling out cement plug. Pressure decreased 40% in 30 minutes. The casing was again tested after drilling out cement plug with 1200'. Pressure decreased 30% in 30 minutes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company anderson oil corp.

Address Box 1097,

Odessa, La Brea

By Winston Payne

Title Mgr