UNITED STATES SUBMIT IN TRIPLICATE.

| (Mag 1983) | DEPAR | TMEN OF TI | HE INTERI | OR (Other Instructi | one on re- | 5. LEASE DESIGNATE | OR AND SERIAL NO. | |
|--|--|--------------------------------|---------------------|---|----------------|---|---------------------|--|
| | GEOLOGICAL SURVEY | | | | LC-032511 (e) | | | |
| (Do not t | | OTICES AND I | | ON WELLS ack to a different reser oposals.) | volr. | 6. IF INDIAN, ALLOT | TES OR TRIBE NAME | |
| 1. | 672 L | | | | | 7. UNIT AGREEMENT | | |
| WELL WELL OTHER 2. NAME OF OPERATOR | | | | | | Langlie-Jal Unit 8. FARM OR LEASE NAME | | |
| | | M CORPORATION | ī | | | | | |
| 3. ADDRESS OF O | | Midland Tox | 70701 | | | 9. WELL NO. 86 | | |
| 1300 Wilco Building, Midland, Texas 79701 4. Location of Well (Report location clearly and in accordance with any State requirements.* See also space 17 below.) | | | | | | 10. FIELD AND POOL, | OR WILDCAT | |
| At surface | a 17 Delow.) | | * 11 • 1 | | _ | Langlie-Matt 11. sec., T., B., M., O SURVEY OR AR | R BLK. AND | |
| . Unit let | ter "0" 430' | FSI & 2310 L | FEL. | | | Sec. 8, 1- 25 | | |
| → Unit Letter "O", 430 FSL & 2310 FEL 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, CR, etc.) | | | | | | 12. COUNTY OR PARI | | |
| • ;= | | 3148' | DF | | | Lea | New Mexic | |
| 16. | Check | Appropriate Box 1 | To Indicate N | ature of Notice, Re | port, or Oil | her Data | | |
| | NOTICE OF INT | ENTION TO: | | | Subseque | TO TROUBE TH | | |
| TEST WATER | SHUT-OFF | PULL OR ALTER CAS | 170 | VATER SHUT-OFF | | REPAIRING | MBLL | |
| FRACTURE TR | <u> </u> | MULTIPLE COMPLET | E | FRACTURE TREAT | | ALTERING | | |
| SHOOT OR AC | 11 | ABANDON* | | shooting or act | | ABANDONA nd Deepen | X | |
| (Other) | ' L J | CHANGE PLANS | | | | multiple completion ion Report and Log : | n on Well | |
| 17. DESCRIBE PROF | OSED OR COMPLETED | PERATIONS (Clearly s | tate all pertinent | details, and give perti | nent dates, in | cluding estimated d | late of starting an | |
| proposed w | work.) * | ctionally drilled, give | Subsurface location | bañ berñecem bac ea u | true verticai | deptus for all mark | ers and zones pert | |
| | | | | • | | | | |
| | | | | and pulled rods | | | | |
| | | | | d deepened to | TD `3755¹ | (6-1/8" hol | e) | |
| | | 1974, Logged | | D 3/51'. 16') of 4 1/2" | OD 10 5# | D-55 linar | tn 3755L | |
| 4. | | | | 50 Sx. Pozmix | | | | |
| 5. | December 24, | 1974, Tested | casing to | 1000# with no | decreas | e in pressur | e . | |
| . 6. | January 7, 1 | 975, perforat | ed Seven-R | livers Queen fo | ormation | v/1 JSPF - 3 | 330 5, 3332 ' | |
| | | | | 3382', 3388', | | | | |
| | | | 477', 3479 | ', '3487', 3493 | 3'-96', 3 | 510', 3523', | 3530-32', | |
| 7. | (Total 35 ho January 8, 1 15% NE Acid. | | Seven-Riv | ers Queen perf | Es. 3330- | 3532 w/1500 | gals. | |
| 8. | | 975, Sand fra | c. Seven-R | ivers Queen fo | ormation | w/40,000 gal | s. 2% KCL | |
| | | | | ock salt as a | | | | |
| | | 19 75, Ran t u b | ing and ro | ds. Well is r | now ready | to be place | d on | |
| | production. | | - | en e | | | | |
| | <i>:</i> | | . ! | | | | | |
| • | | | | į | | | | |
| | ······································ | | | | -a | | | |
| 18. I hereby certii | ly that the foregoing | is true and correct | • | | | - | 4 | |

TITLE Gas Measurement Analyst DATE 1-17-75 (This space for Federal or State office use) ACCEPTED FOR RECORD *See Instructions on Reverse Side HOBBS, NEW MEXICO