

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on
reverse side)Form approved.
Budget Bureau No. 42-R1424.5. LEASE DESIGNATION AND SERIAL NO.
LC 032511A

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/> Water Injection Well	7. UNIT AGREEMENT NAME Langlie Jal Unit
2. NAME OF OPERATOR Union Texas Petroleum Corporation	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR 1300 Wilco Bldg., Midland, Texas 79701	9. WELL NO. 83
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 660' FWL	10. FIELD AND POOL, OR WILDCAT Langlie-Mattix
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3160' GL
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 9 T-25-S, R-37-E
	12. COUNTY OR PARISH Lea
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐


SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒

(NOTE: Report results of multiple completion or Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. MIRUSU - Install BOP, POH with short string of tubing.
2. Packer would not unseat. Tubing stuck. Backed off tubing at 1918'. POH.
3. WIH with string shot @ 2970'. Came out of hole with 1052' of tubing. Top of fish at 2970'.
4. Fished and milled on fish. Left packer in hole with unknown amount of tubing. Top of fish at 3265'.
5. Loaded hole with sand to 3155'. Set cement retainer at 2800'.
6. Squeezed with 300 sacks of cement. Squeeze did not hold.
7. Re-squeezed with 300 sacks cement at maximum pressure of 1500 psi. Squeeze held.
8. Temporarily abandoned well, pending engineering evaluation. 5/27/82.



18. I hereby certify that the foregoing is true and correct

SIGNED

Richard A. Glass

TITLE

Production Services

DATE

6-30-82

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY

(ORIG. SGD.) DAVID R. GLASS

CONDITIONS OF APPROVAL

NOV 1 1982

DATE

U.S. GEOLOGICAL SURVEY

ROSWELL, NEW MEXICO *See Instructions on Reverse Side

RECEIVED

NOV 2 1982

O.C.D.
HOBBS OFFICE

RECEIVED

JUL 1 1982

O.C.D.
HOBBS OFFICE