



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. LC 032501 b
Unit MTU

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			
Notice of Intention to Cleanout and Free			X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 3, 1958

Shales 8-19

Well No. 2 is located 990 ft. from N line and 2310 ft. from W line of sec. 19

18 1/4 Sec. 19
(1/4 Sec. and Sec. No.)

25S
(Twp.)

37E
(Range)

1804
(Meridian)

Jalisco
(Field)

Los
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 3107 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well has been TSD since 5-1-58. TD 3000' sand, DF 10', Elev 3107'.
Pay Yates open hole 2800-3000'. Cag pt 2700'.

To restore this well to commercial production it is proposed to cleanout this well to TD and treat open hole w/2,000 gals acid and 20,000 gals crude w/3/4 lb sand, 1/20 lb Adomite per gal.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 68

Demeco, New Mexico

By _____

Title District Superintendent