

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

WELL API NO.  
30-025-11642

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.  
408175

7. Lease Name or Unit Agreement  
Name:

SOUTH LANGLIE JAL UNIT

8. Well No.  
#18

9. Pool name or Wildcat  
JAL TANSILL YATES 7 RIVERS

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other WATER INJECTION WELL

2. Name of Operator  
CHAPARRAL ENERGY, INC.

3. Address of Operator  
701 CEDAR LAKE BLVD., OKLAHOMA CITY, OK 73114

4. Well Location

Unit Letter \_\_\_\_\_ E: 1980 feet from the NORTH line and 990 feet from the WEST line

Section 17 Township 25S Range 37E NMPM LEA County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3105' RKB, 3097' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☒ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: MECHANICAL INTEGRITY TEST ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.


1. PULLED TUBING AND PACKER.

2. SET CIBP @ 3097' AND CAPPED WITH 2 SX CEMENT.

3. RAN MECHANICAL INTEGRITY TEST ON DECEMBER 5, 2001 AND TUBING-CASING ANNULUS HELD 540 PSIG FOR 30 MINUTES (COPY OF PRESSURE CHART ATTACHED). TEST WAS WITNESSED BY E. L. GONZALES.

4. BASED ON SUCCESSFUL MIT TEST, CHANGE IN CLASSIFICATION FROM ACTIVE TO TA STATUS IS REQUESTED.

This Approval of Temporary  
Abandonment Expires 1/4/07



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ralph W. Everett TITLE OPERATIONS ENGINEER DATE 12/27/01

Type or print name RALPH W. EVERETT  
(This space for State use)

Telephone No. (405) 478-8770 ext. 1278

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
Conditions of approval, if any:

5  
2  
5

11 MIDNIGHT

Chapman Drury  
South Long's Gul unit #182

Swky NW 1/4 37E  
Sec 17-25S  
Rear corner N.M.

GRAPHIC CONTROLS CORPORATION  
BUFFALO, NEW YORK

*[Signature]*

12-5-01

BR 200

*[Signature]*

12-5-01

12215478010112181630  
JAN 2002  
RECEIVED  
Hobbs  
OCO

NOON

121510 AND 120000  
A.B. TAYLOR  
121510