

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-11647
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. 408175
7. Lease Name or Unit Agreement Name: SOUTH LANGLIE JAL UNIT
8. Well No. #15
9. Pool name or Wildcat JAL TANSILL YATES 7 RIVERS

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other WATER INJECTION WELL	
2. Name of Operator CHAPARRAL ENERGY, INC.	8. Well No. #15
3. Address of Operator 701 CEDAR LAKE BLVD., OKLAHOMA CITY, OK 73114	9. Pool name or Wildcat JAL TANSILL YATES 7 RIVERS
4. Well Location Unit Letter C: 990' feet from the NORTH line and 1980' feet from the WEST line Section 17 Township 25S Range 37E NMPM LEA County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3118' DF, 3110' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Mechanical Integrity Test ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Ran mechanical integrity test on August 16, 2001 and tubing-casing annulus held 550 psig for 30 minutes (copy of pressure chart attached). Test was witnessed by B. Hill with OCD.
2. Based on successful MIT test, change in classification from active to TA status is requested.

This Approval of Temporary
Abandonment Expires 10/10/04

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ralph W. Everett TITLE OPERATIONS ENGINEER DATE 09/27/01


Type or print name RALPH W. EVERETT

Telephone No. (405) 478-8770 ext. 1278

(This space for State use)

APPROVED BY _____ TITLE _____ DATE _____

Conditions of approval, if any:



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

Chaparral Energy

South Langley
Jal Ut.

#15

8-16-01

BR 2221

C-17-25-37

A+B

1000#

60 MEN.

last Cal. 9-12-00

Amer. Mtr.

EST!