WELL REMEDIAL REPORT N... MEXICO OIL & GAS ENGINEERING C. MITTEE BOX 127 HOBBS, NEW MEXICO

Company Hubbs Call & Reclining Co. Address Rox 2347, Hebbs, M. Date Date Lease Living Co. Lease Living Co. Well # 2 Unit Sec. T. 2388. 78 Pool Weller
1954 APR 14 PM 2
NATURE OF WORKOVER Drill Deeper Cement plugback Plastic plugback Set Liner Prill Coment squeeze Plastic squeeze Set Packer Acidize Shoot
FOR PURFOSE OF Increase production, Oil Gas Shut off water Shut off gas
RESULTS SUMMARY Complete success Partial success Failure
DATE Workover started Completed Completed
WELL DATA D.F. elev. 347 Completion date Prod. formation
Oil String inch pipe set at 3260
Depth of hole before After Mo
Formation packer set atwith perforations abovebelow
inch liner set. Top Bottom Cemented w. sax,
and perforated with holes from to
Section squeezed from to with sacks cement or
gallons plastic. Maximum pressure used P.S.I.
INSTRUMENTS RUN IN CONJUNCTION WITH OR PRIOR TO WORKOVER Temperature bombElectric logDowell pilotGamma ray Water witchHole CaliperDia-logOther
RESULTS DETAIL Oil production Bbls./day Water Production Bbls./day Gas Production M.C.F./day Gas oil ratio
REMARKS: Drilled Daker 3-5 padeer et 32351. Freeted (meen Zone 3260-3400) 4th
6,000 gallene Petrofree with 1/ send per gallen. Needsom and minimum injection
presences 3500 and 3600f. Sweet hoolers la paster and Wilson holddom at 3000f.