# HIMBLE OIL & REFINING COMPNAY'S

### J. T. Lanchart #1

~

SW 1/4, Section 21, Township 25-South, Range 36-East, Lee County, New Mexico.

### DEVIATION SURVET'S

| syto | test     | <b>\$</b> \$ | 14751 |   | Hole straight<br>Hole straight |
|------|----------|--------------|-------|---|--------------------------------|
| *    |          | <b>#</b>     | 2180* | - | Deviation 3 degrees            |
| 11   | <b>●</b> |              | 24251 |   | Deviation 5 degrees            |

## SCHLUMRERGER TESTS

From 2750' to 2850' and from 2930' to 5000' showed considerable gas. From 3027' to 3047' possibility of formation carrying eil.

#### DRILL STEN TESTS

Tested with Halliburton Testing tool from 2988' to 3097' - showed 100,000 cubis feet of gas and 210' of drilling must.