

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANITARY	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-101
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR NOTICES TO WELL OWNERS TO ABANDON OR TO RE-ENTER A WELL IN A DIFFERENT RESERVOIR.
USE THESE FORMS FOR NOTICES TO WELL OWNERS TO ABANDON OR TO RE-ENTER A WELL IN A DIFFERENT RESERVOIR.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

1. Name of Operator
Atlantic Richfield Company

2. Address of Operator
P. O. Box 1710, Hobbs, New Mexico 88240

3. Location of Well
UNIT LETTER **B** **660** FEET FROM THE **North** LINE AND **1650** FEET FROM
East THE **23** LINE, SECTION **25-S** TOWNSHIP **37-E** RANGE **37-E** NMPM.

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

7. Unit Agreement No.

6. Farm or Lease Name
Wimberly WN

9. Well No.
7

10. Field and Pool, or Wildcat
Justis-Blinbry

12. County
Lea

15. Elevation (Show whether DF, RT, GR, etc.)
3094 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <u>Casing Leak Survey</u> <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-15-77 cellar was dug out to expose the outlets of braden head from the first sting of pipe cemented in the well and all subsequent heads, including the tubing head. The surface and casing was piped to ground level with 2" pipe. The surface and casing valves were stenciled "Sur." and "Csg.". The above work was performed in accordance with NMOCC letter dated 7-8-77. Work was inspected by Eddie Seay with NMOCC on 8-9-77.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie Seay TITLE Sr. Dist. Prod. Supvr. DATE 8-17-77

APPROVED BY Eddie Seay TITLE OIL & GAS INSPECTOR DATE AUG 24 1977

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
JAN 10 1968
CIVIL SERVICE COMMISSION
WASHINGTON, D. C.