Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

FEB 03 1993

DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION

LL API NO.		
	30-025-11722	

P.O. Box 208	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico	87504-2088 30-025-11722
DISTRICT III	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELL	18
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN (OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PER (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
1. Type of Well: Oil. QAS	Ida Wimberley
WELL OTHER Salt Wa	
2. Name of Operator	8. Well No.
ARCO OIL AND GAS COMPANY 3. Address of Operator	13
P. O. Box 1610, Midland, Texas 79702	9. Pool name or Wildcat San Andres
4. Well Location	
Unit Letter M: 330 Feet From The West	Line and 330 Feet From The South Line
Section 24 Township 25S Ran	Re 37E NMPM Lea Court
10. Elevation (Show whether D	PF. RKB, RT. GR, etc.)
11. Check Appropriate Box to Indicate N	
NOTICE OF INTENTION TO:	fature of Notice, Report, or Other Data
	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	CASING TEST AND CEMENT JOB
OTIES -	
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and work) SEE RULE 1103. 	give pertinent dates, including estimated date of starting any proposed
12-19-92 RUPU. Backed off 3-1/2" tubing & POH.	TOF at 965. Recovered 3-1/2" RBP, PKR and
misc I 1/2" tbg & fishing tools stuck	in $3-1/2$ " that $f/306-362$. Attempt a scrow back
onto 3-1/2" tbg W/no success. Ran tra	cer Survey. No fluid loss below TOF @ 956
Accempt to screw back into 3-1/2" W/n	o success.
P&A'd San Andres 4070-4165' as follows:	
Procedure approved by Ray Smith 12-24-92. Plugs	witnessed by Charlie Perrin.
Plug <u>Interval CMT Remarks</u> 1 3325-4000 25 sx Set CIBP @ 4000	
1 3325-4000 25 sx Set CIBP @ 4000 2 2520-3195 25 sx Spot.	O'. Plugs witnessed by Charlie Perrin.
3 1634-2309 25 sx Spot.	
4 950-1110 25 sx	
5 700-950 100 sx \(\text{MOC overnight}\)	& tag @ 751.
6 0-100 60 sx (return	n Seven Rivers-Queen to prod. RDPU 10-27-92.
I hereby certify that the information above is true and complete to the best of my knowledge and bel	ief.
SKONATURE Ken au Sofnell TITLE	Regulatory Coordinator 1-8-93
TYPEOR PRINT NAME Ken W. Gosnell	915/688-5672 TELEPHONE NO.
(This space for State Use).	

- TITLE -

APPROVED BY-

Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised	1-1-8

Distant Office					
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION		WELL API NO.		
P.O. Box 2088 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 P.O. Box 2088 Santa Fe, New Mexico 87504-2088		30-025-11722 5. Indicate Type of Lease			
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			STATE FEE 6. State Oil & Gas Lease No.		
O INDOVINCE					
(DO NOT USE THIS FORM FOR PRO DIFFERENT RESER	CES AND REPORTS ON WE POSALS TO DRILL OR TO DEEPE! VOIR. USE "APPLICATION FOR PE 101) FOR SUCH PROPOSALS.)	N OR PLUG BACK TO A	7. Lease Name or Unit Agreemen	zt Name	
1. Type of Well: OIL GAS GAS		Hater Disposal	Ida Wimberley		
2. Name of Operator	OTHER SALL	Mater Disposar	8. Well No.		
ARCO OIL AND GAS COMPA	ANY		13		
3. Address of Operator P. O. Box 1610, Midlan	nd. Texas 79702		9. Pool name or Wildcat San Andres		
4. Well Location Unit Letter	<u>-</u>	Line and 330	Feet From The	outh	
		075		Line	
: Section 24	Township 25S R	tange 37E	NMPM Lea	County	
	3079 DF	, D1 , 10tb , 111 , O11, 642.			
11. Check A	Appropriate Box to Indicate	Nature of Notice. R	eport, or Other Data		
NOTICE OF INT	ENTION TO:	SUE	SEQUENT REPORT	OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING O	:ASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	G OPNS. DPLUG AND A	ABANDONMENT	
PULL OR ALTER CASING		CASING TEST AND C	EMENT JOB		
OTHER: P&A San Andre	es Zone X	OTHER:	·	L	
12. Describe Proposed or Completed Operation work) SEE RULE 1103.	ions (Clearly state all persinent details, a	and give pertinent dates, incli	iding estimated date of starting any p	roposed	
<i>'</i>	off 3-1/2" tubing & PO	H. TOF at 965.	Recovered 3-1/2" RBP	. PKR and	
misc 1 1/2" tb onto 3-1/2" tb	og & fishing tools stu og w/no success. Ran t	ck in 3-1/2" the racer Survey. No	r f/306-362. Attemp	to screw back	
Proposeto	rew back into 3-1/2" w	/no success.			
P&A'd San Andres 4070-41 Procedure approved by Ra		gs witnessed by	Charlie Perrin.		
Plug <u>Interval</u>	CMT Remarks				
		000'. Plugs with	nessed by Charlie Pe	rrin.	
2 2520-3195 3 1634-2309	25 sx Spot. 25 sx Spot.				
4 950-1110	25 sx				
5 700-950	100 sx WOC overnigh	t & tag @ 751.			
6 0-100	<u>60 sx (ret</u>	urn Seven River	s-Queen to prod. RDP	U 10-27-92.	
I hereby certify that the information above is true			0 11 1 1 1	0.00	
SKINATURE REMAND GOS	nel r	mr Regulator	Coordinator 1	8-93	
TYPEOR PRINT NAME Ken W. Gosn	ell	91:	5/688-5672 TELEPHON	E NO.	
(This space for State Use)			FI	EB 03 1993	
# ≤ 1 t€ ∰ 1 1 ° ·	(9 3) - 11	TILE	DATE		