

GETTY OIL COMPANY
A.B. Coates "C" Well No. 17
Justis Injec Unit Well No. 117
1971 Packer Leakage Test
Chart No. 1

PRINTED IN U.S.A.

shut in both zones
Justis Ellenburger
Justis McKee


Precision Charts
ROSS-MARTIN CO. TULSA, OKLA. 74101


WELL NUMBER	
TEST POINT	IN
DATE TESTED	BY
RE	

FX-898718
0-3000-120

TIME TESTED	
DATE TESTED	BY
RE	

GETTY OIL COMPANY
A.B. Coates "C" Well No. 17
Jostis McKee Unit Well No. 117
1991 Packer Leakage Test
Chart No. 2





GETTY OIL COMPANY
A.B. Coates "B" Well No. 17
Justice McKee Unit Well No. 117
1971 packer leakage test
Chart No. 3

Shot in Justice McKee
Justice Ellendurges

Precision Charts
ROSS-MARTIN CO. TULSA, OKLA.
JUL 11 1971

12 NIGHT

11 P.M.

6 P.M.

7 P.M.

8 P.M.



9 P.M.


10 P.M.

11 P.M.

GETTY OIL COMPANY
A.B. Coates & Well No. 17
Jostis McKee Unit Well No. 117
1971 Packer Leakage Test
Chart No. 4

Pump Jostis Ellenburger
Jostis McKee





JUSTIS ELLENBURGER GOR TEST

ARCCO
RECORDING CHARTS

LEASE METER _____

ON _____ M _____

LOCATION _____ 19 _____

REMARKS _____

PLATE _____

OFF _____ M _____

P100 W100
(M-100-H)
Los Angeles, California