

RICE Engineering Corporation

122 WEST TAYLOR TELEPHONE (505) 393-9174

HOBBS, NEW MEXICO 88240

March 29, 1990

State of New Mexico
Oil Conversation Division - District I
P. O. Box 1980
Hobbs, NM 88241

RE: Justis SWD "N" Well No.26
SE/4 SW/4 Sec.26,T25S,R37E
Lea County, New Mexico
(Justis SWD System)

Gentlemen:

We have been informed by your office that a recent casing annulus integrity test chart and C-103 Sundry Report were not filed regarding the above mentioned SWD well. We apologize for the oversight of not filing C-103 with your office. Enclosed please find C-103 duly completed for the workover that converted this well to a SWD well.

An annulus integrity test chart was run on 11-7-1989 upon completion which would have been filed with C-105. In any case, we are forwarding your office a copy of this test chart. We believe the reason Justis SWD "N" Well No.26 was not included in your last bradenhead pressure test survey with rest of Rice operated SWD wells was the approval date of C-104 on 10-20-1989 after your directives were issued. However, we will be happy to comply with your request to conduct a more recent annulus integrity test and record it on chart should you require.

Please contact us if we can be of assistance in this matter.

Yours very truly,
RICE ENGINEERING CORPORATION


S. A. Haktanir
Division Manager

SAH/

Enclosures