



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**
Lease No. **022579(0)**
Unit **Lease**

1961 JUN 19 AM 5:30

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	X
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 15, 1961

Well No. **Carlson B 26** is located **200** ft. from **N** line and **1650** ft. from **E** line of sec. **26**
NE 1/4 of SW 1/4 Sec. 26 **25S** **37E** **N. H. P. M.**
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Justin **Lee** **New Mexico**
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3044** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Swab tested Blinberry perf. at 5110' to 5162'
 1 bbl. per hr. out 60%. Drilled up plug at 5418'.
 Cleaned out to 5545'. Swabbed 4 to 6 bbl. per
 hr. from perf. 5470' to 5518' out 80%. Set
 production packer at 5085'.
 Well tests - Blinberry - 28 bbl. oil
 " 48 bbl. water
 Padlock 4 bbl. oil
 " 4 bbl. water

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Westates Petroleum Company**
 Address **Box 1301**
Jal., New Mexico
395-2600
 By **J. E. Chaffin**
 Title **Production Superintendent**