



(SUBMIT IN TRIPLICATE)

Land Office Las CrucesLease No. 032579(e)

UNITED STATES GEOLOGICAL SURVEY
DEPARTMENT OF THE INTERIOR

MAY 17 AM 10:18

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. Carlson B 26 is located 2310 ft. from M line and 1670 ft. from E line of sec. 26
NE 1/4 of SW 1/4 Sec. 26 25N 77E N.H.P.M.
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Justin Las New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3044 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Our recent acid job failed to produce any increase in production, in the Blintry zone. (March 24, 1961)

We propose to snub test 5110' to 62'. Clean out and remove bridge plug at 5418'. Snub test perf. at 5470' to 5518'. Put well on production. All work will be performed according to State and Federal regulations.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Montrose Petroleum CompanyAddress Box 1381Al., New Mexico395-2600By H.E. ChaffinTitle Production Superintendent