



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**
Lease No. **032579 (f)**
Unit **Harrison**

RO-762 **SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 13, 1956

Well No. 2 is located 660 ft. from N line and 660 ft. from W line of sec. 27
C-W 1/4 NW 1/4 Sec. 27, 25 S 37 E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Langlie-Mattix Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3048 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We ran 3537' of 7", 23# casing. Cemented with 200 sacks. Through 2-staged, set at 926', we used 100 sacks of neat cement. Plugged down at 3:00 A.M. 1-11-56. Waited 48 hours. Pressured up with 1000# for 30 minutes. No leaks.

RECEIVED

JAN 23 1956

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company R. OLSEN, 2811 Liberty Bank Bldg. Oklahoma City, Okla.

Address Drawer #2

Jal, New Mexico

By R. Olsen

Title Regional Manager