CONSERVATION COMMILLON

scellaneous Reports

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations results of shooting well, results of test of casing shut off, result of plugging of well, and other important opera-

	THETCH OF 144	ture of repo	rt by checking below.		
EPORT ON BEGINNING I	DRILLING		REPORT ON RE	PAIRING WELL	1
EPORT ON RESULT OF S	SHOOTING OR		REPORT ON PU	LLING OR OTHER	WISE
EPORT ON RESULT OF T			REPORT ON DE	EPENING WELL	
EPORT ON RESULT OF	PLUGGING OF WE	LL X			
				M	<u> </u>
	.,	3-23-51	Jal, 1	iem extco	Place
L CONSERVATION COMMINTA FE, NEW MEXICO. entlemen:			and under the heading	r mated above at the	
ollowing is a report on the	work done and the	results obtain	Dawson	Well No	in the
D. OLSEN SOURCE W/2 NE SE NE	r Operator	<u>.</u>	Lease r 25 S	р 37%	NWBW
Lenglie-Maitix	Field	Les		.,	Counts
Langlie-Maitix he dates of this work were	Field	Starte	inia 5-5-51	shed 3-13-51	
100 sacks mid was mi	ixed, tubing r	un to 240	i around, raisi	ated to surfac	150'.
100 sacks mud was mile sanks coment plug 1893' of 5½ casing with mud then a 5 sacks with a short	ixed, tubing r g was pumped a was recovered ack cement plu joint of 3" p	un to 240 nd washed as was 70 g put in ipe welde	10', mud circulate around, raisis 17' of 7 5/8 car top. A cap was ad a d standing	ated to surface ng the tubing : sing. Hole was swelded on the as a marker.	150'. s refilled to e 8 5/8" suri
100 sacks mud was mile sanks coment plug 1893' of 5½ casing with mud then a 5 sacing with a short	ixed, tubing r g was pumped a was recovered ack cement plu joint of 3" p	un to 240 nd washed as was 70 g put in ipe welde	10', mud circulate around, raisis 17' of 7 5/8 car top. A cap was ad a d standing	ated to surfacing the tubing ing. Hole was welded on the as a marker.	150'. s refilled to
100 sacks mud was mile sanks coment plug 1893' of 5½ casing with mud then a 5 sacing with a short	ixed, tubing r g was pumped a was recovered ack cement plu joint of 3" p	un to 240 nd washed as was 70 g put in ipe welde	i around, raising of 7 5/8 cartop. A cap mand a d standing	ated to surface ng the tubing ing. Hole was a welded on the as a marker. Chi.	s refilled to e 8 5/8" suri
100 sacks mud was mile sacks coment plug 1893' of 52 casing with much them a 5 sacasing with a short. G.J. Subscribed and sworn between the sacks of the sacks	ixed, tubing r g was pumped a was recovered ack cement plu joint of 3" p	un to 240 nd washed as was 70 g put in ipe welde	i around, raising of 7 5/8 can top. A cap was ad a d standing of 8 Company	ated to surface ng the tubing ing. Hole was a welded on the as a marker. Chi.	s refilled to e 8 5/8" suri
100 sacks mud was mile sanks coment plug 1893' of 5½ casing with much them a 5 sacing with a short. (itnessed by	ixed, tubing regular to the second recovered ack cement plugions of 3" property of the second recovered ack cement plugions of 3" property of the second recovered ack cement plugions of the second recovered	un to 244 nd washed as was 76 g put in ipe welde R. OL:	i around, raising of 7 5/8 care top. A cap was ad a d standing of 8 Company I hereby swear or a is true and correct.	ated to surface ng the tubing ing. Hole was a welded on the as a marker. Chi.	s refilled to e 8 5/8" suri
100 sacks mud was mile sanks coment plug 1893' of 5g casing with much them a 5 sacasing with a short. Witnessed by	ixed, tubing r g was pumped a was recovered ack cement plu joint of 3" p	un to 244 nd washed as was 76 g put in ipe welde R. OL:	i around, raisi i top. A cap was top. A cap was ad a d standing SEN OIL COMPANY Company I hereby swear or a is true and correct. Name	ated to surface ing the tubing ing. Hole was a welded on the as a marker. Chi.	s refilled to e 8 5/8" suri ef Clerk Title mation given abov
100 sacks mud was mile sanks coment plug 1893' of 5½ casing with much them a 5 sacing with a short. (itnessed by	ixed, tubing regular was recovered as recovered sok cement plugion of 3" p ENOS Name Notary I	un to 244 nd washed as was 76 g put in ipe welde R. OL:	i around, raisi i top. A cap was d a d standing SEN OIL COMPANY Company I hereby swear or a is true and correct. Name Position	the tubing ing. Hole was welded on the as a marker. Chi- Chi- Chi- Chi- Chi- Chi- Chi- Company or Operation	s refilled to e \$ 5/8" suri ef Clerk Title mation given abov
100 sacks mad was at 10 sanks coment plug 1893' of 5½ casing with much then a 5 sacks made with a short witnessed by	ixed, tubing regular was recovered as recovered sok cement plugion of 3" p ENOS Name Notary I	un to 244 nd washed as was 76 g put in ipe welde R. OL: Public Sept. 2, 1953	i around, raising around, raising of 7 5/8 care top. A cap was and a d standing sen OIL COMPANY Company I hereby swear or a is true and correct. Name Position R Representing	the tubing the tubing. Hole was a warker. Chi. Chi. Chi. Chi. Chi. Chi. Company or Operate	s refilled to e \$ 5/8" suri ef Clerk Title mation given abov

mills.