

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

054667

Serial Number

Lease

Lease or Permit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT RECORD OF SHOOTING	
NOTICE OF INTENTION TO CHANGE PLANS	<input checked="" type="checkbox"/>	RECORD OF PERFORATING CASING	
NOTICE OF DATE FOR TEST OF WATER SHUT-OFF		NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING	
REPORT ON RESULT OF TEST OF WATER SHUT-OFF		NOTICE OF INTENTION TO ABANDON WELL	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO SHOOT		SUPPLEMENTARY WELL HISTORY	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

8-43

19 37

Following is a ~~notice of intention to do work~~ ~~report of work done~~ on land under ~~permit~~ ~~lease~~ described as follows:

New Mexico

Lea County

Langlie

(State or Territory)

(County or Subdivision)

(Field)

Well No.

C NE 1/4 33

253

37E

N.M.P.M.

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

The well is located 660 ft. $\begin{Bmatrix} N \\ S \end{Bmatrix}$ of $\begin{Bmatrix} N \\ S \end{Bmatrix}$ line and 1900 ft. $\begin{Bmatrix} E \\ W \end{Bmatrix}$ of $\begin{Bmatrix} N \\ S \end{Bmatrix}$ line of sec. 33-25-37

The elevation of the derrick floor above sea level is 3016 ft.

DETAILS OF PLAN OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work.)

Well drilled to 2355'. Had base of salt (driller's log) at 2305'. 9-5/8" OD - 40# API Grade C Seamless casing cemented at 2355' with 800 sacks common cement. Operations to test cement and casing to start 8-24-27.

15" OD - 40# Lapweld surface casing was cemented at 256' with 350 sacks common cement. After setting 48 hrs cement plug was drilled out and hole bailed dry. Hole was still dry after setting 48 hrs.

Approved _____
(Date)

Company Anderson-Prichard Oil Corp.

By *Huston Payne*

Title Manager Production Dept.

Title _____
GEOLOGICAL SURVEY

Address _____

Address Box 1097, Hobbs, N.M.

NOTE.—Reports on this form to be submitted in triplicate to the Supervisor for approval.

100-100000

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS OF FIELD

REPORT OF FIELD OFFICER IN CHARGE
TO THE DIRECTOR, BUREAU OF LAND MANAGEMENT
WASHINGTON, D. C.
DATE: [illegible]
TO: [illegible]
FROM: [illegible]
SUBJECT: [illegible]

[illegible text]

[illegible text]

[illegible text]

[illegible text]

[illegible text]

[illegible text]