Form 9-331 (May 1963)

14. PERMIT NO.

UN TD STATES

	SUBMIT	IN	TRIPL
`	(Other i		uctions
≺	verse side	. 1	

Form approved. Budget Bureau No. 42-R1424.

T-25-S, R-37-E

12. COUNTY OR PARISH | 13. STATE

DEPARTMEN. OF THE INTERIOR (Other Instructions)	5. LEASE DESIGNATION AND SERIAL NO.
GEOLOGICAL SURVEY	LC 054667
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL X GAS OTHER	7. UNIT AGREEMENT NAME
NAME OF OPERATOR	8. FARM OR LEASE NAME
Texas Pacific Oil Company, Inc.	Gregory "A"
ADDRESS OF OPERATOR	9. WELL NO.
P. O. Box 4067, Midland, Texas 79701	5
LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)	10. FIELD AND POOL, OR WILDCAT
At surface	Langlie Mattix
1980' FSL & 660' FEL	11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA Unit I, Sec. 33

Check Appropriate Box To Indicate Nature of Notice Report or Other Data

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3004 DF

	Cire	ck / tppropriete box to it	10100	tale radiole of radice, kepoli, of Oliver Dala	
NOTI	CE O	F INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF REPAIRING WELL	
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT ALTERING CASING	
SHOOT OR ACIDIZE		ABANDON*		SHOOTING OR ACIDIZING ABANDONMENT*	
REPAIR WELL		CHANGE PLANS		(Other) Well Status X	
(Other)				(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

This well was shut-in on 4/30/76 due to mechanical failure. It had been producing 2 BOPD, 1 BMPD & 34 MCFPD. Although the well was producing in paying quantities prior to the failure, insufficient primary reserves remain to payout remedial costs. This well should not be P&A'd at this time because of it's secondary recovery potential. There are five secondary recovery units located within six miles of this well. The closest being Mobil Oil Co.'s Langlie Mattix (Queen) Unit approximately three miles to the northeast. Present plans are to initiate secondary recovery operations on this lease in late 1980.

> This approval of temporary 4-30-29 abandonment expires-

SIGNED SIGNED	TITLE Reg. Oper. Supt. (West) - 10/19/78
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE
7	*See Instructions on Reverse Side, GEOLOGICAL SURVEY W. HOBBS, NEW MEXICO