

Submit 3 copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 12221
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DRINKARD UNIT
8. Well No.	3
9. Pool Name or Wildcat	DOLLARHIDE TUBB DRINKARD
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3168' DF

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER INJECTOR

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
P.O. BOX 730, HOBBS, NM 88240

4. Well Location
Unit Letter D : 660 Feet From The NORTH Line and 660 Feet From The WEST Line
Section 19 Township 24S Range 38E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3168' DF

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ REQUEST TA STATUS EXTENSION

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

A mechanical integrity pressure test was performed on the subject well on 6/7/95.
The pressure test was to 520 psi for 30 minutes and the casing held.

Texaco E & P Inc. respectfully requests a five year extension of the TA status.

The original pressure chart is attached to this form; a copy can be found on the reverse side.

Justification: The West Dollarhide Drinkard Unit #3 lies within the unitized boundary of the unit. Texaco would like to hold this wellbore in TA status for future utility as an injection well.


This Approval of Temporary
Abandonment Expires

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Darrell J. Carriger TITLE Engineering Assistant DATE 7/12/95
TYPE OR PRINT NAME Darrell J. Carriger Telephone No. 397-0426


(This space for State Use)

APPROVED BY _____ TITLE _____ DATE JUL 17 1995
CONDITIONS OF APPROVAL, IF ANY:



RECEIVED

1905



DAY 6

NIGHT 6

TEXAS
INSTRUMENT ENGINEERS

TEST TIME
TEST TIME PER UNIT TEST

BR-2221
B 0-1000-8

0-1-5

WEST KAPD 122212Z
TEXACO
00-025-122212Z
006 008 009