

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-9519	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name West Dollarhide Drinkard Sand Unit	
2. Name of Operator Texaco Producing Inc. (Sirgo-Collier, Inc.)		8. Farm or Lease Name	
3. Address of Operator P.O. Box 1060, Eunice, NM (P.O. Box 3531, Midland, TX 79702)		9. Well No. 34	
4. Location of Well UNIT LETTER M, 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 29 TOWNSHIP 24S RANGE 38E NMPM.		10. Field and Pool, or Wildcat Dollarhide Drinkard	
15. Elevation (Show whether DF, RT, GR, etc.) 3182' KB 3170' GL		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-15-88 MIRU PU. Tag up @ 2031', Mill on fish, made 1' to 2032'.  
8-16-88 Milling @ 2035', Made 3'.  
8-17-88 Milling @ 2044', Made 9'.  
8-18-88 Ran impression block, shows 5½ stub looking up. PU broke down.  
8-19-88, 21,22-88 SI, waiting on replacement pulling unit.  
8-23-88 MIRU PU. Tag up @ 2039'. Mill on fish, no footage made.  
8-24-88 Ran impression block, show collapsed 5½" csg.  
8-25-88 Ran overshot. Recovered 2 pieces 5½" csg. Reran grapple, no recovery.  
8-26-88 Ran washpipe, tag @ 2033', Made 6' to 2039'. POH.  
8-27-88 Reran washpipe, made 1'.  
8-28-88 SI.  
8-29-88 POH, ran impression block, show 5½" csg.  
8-30-88 Ran washshoe over fish. Mill to 2040'.  
8-31-88 Ran blade bit on tbg, tag @ 2038', drill to 2076' inside 5½" csg.  
9-1-88 Drill to 3860'. Scale & iron sulfide inside 5½". Getting stuck.  
9-2-88 Drill to 3245'. Cannot move up or down. Received permission to plug. Pump 150 sx.  
Lite, 8# salt, ¼# flocele, tail 100 sx. Neat. Circ. 100 sx. to pit.  
9-3,4,5-88 SI for cement.  
9-6-88 Set dry hole marker, clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Walter J. Sirgo TITLE Vice-President DATE 9-19-88  
Sirgo-Collier, Inc.

APPROVED BY R. A. Linder TITLE OIL & GAS INSPECTOR DATE OCT 21 1988

CONDITIONS OF APPROVAL, IF ANY:

8

SEP 20 1988

OCD  
HOBBS OFFICE