

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		<p>5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p> <p>5. State Oil & Gas Lease No.</p>
<p>1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER</p> <p>2. Name of Operator Amerada Hess Corporation</p> <p>3. Address of Operator P. O. Drawer D, Monument, New Mexico 88265</p> <p>4. Location of Well UNIT LETTER M, 990 FEET FROM THE South LINE AND 990 FEET FROM THE West LINE, SECTION 33 TOWNSHIP 24-S RANGE 37-E NMPM.</p>	<p>7. Unit Agreement Name</p> <p>8. Farm or Lease Name L. M. W. U.</p> <p>9. Well No. 002</p> <p>10. Field and Pool, or Wildcat Langlie Mattix</p>	<p>15. Elevation (Show whether DF, RT, GR, etc.)</p> <p>12. County Lea</p>

<p>16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p>	
<p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>SUBSEQUENT REPORT OF:</p> <p>PLUG AND ABANDON <input type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Completed 9-17-76

Pulled production equipment, ran bridge plug & pkr., set bridge plug at 3287' & pkr. at 3272'. Spotted 5 sks. sand on top of plug & tested plug w/1200# press. Held OK. Re-set pkr. at 2989' & squeezed Jalmat zone thru 7" csg. perf. fr. 3117' to 3196' w/150 sks. cement with additives. Tested w/1000# press. Held OK. Drld. out cement inside 7" csg. fr. 3061' to 3196' & tested w/500# press. Held OK. Washed sand fr. bridge plug, pulled bridge plug. Washed & circ. open hole clean to 3543'. Acidized open hole fr. 3363' to 3543' w/2500 gal. 15% acid. Re-ran production equipment.

Test prior to work: 9-7-76 - Pumped 6 b.o. & 51 b.w. on 11-34" SPM.

Test subsequent to work. Not producing at present.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E. B. Trishes TITLE Supv. Adm. Ser. DATE 12-2-76

Orig. Signed by Jerry Sexton TITLE Dist 1, Supv. DATE 12-2-76

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 1973

OFFICE OF THE ATTORNEY GENERAL
STATE OF NEW YORK