

APPROVED

Form 9-331a
(Feb. 1951)

AUG 1 1963

(SUBMIT IN TRIPLICATE)

Budget Bureau No. 42-R356.4.
Approval expires 12-31-60.

E. G. HUBBLE
ACTING DISTRICT ENGINEER
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 6 062133
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Midland, Texas 12 June, 19 63

Well No. 1 is located 660 ft. from 1000 line and 1880 ft. from E line of sec. 14
14 (Sec. and Sec. No.) 25-S (Twp.) 15-E (Range) N10W (Meridian)
Wildcat (Field) Lee (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Lease designated Sun-G. A. Federal.

7 inch casing cement 350 feet.

Well was plugged in the following manner: 20 foot undrilled cement plug was left at the bottom of the casing. Casing was filled with mud and 10 sack cement plug was set at the top.

A P.C.G. marker was set and the location cleaned up.

ILLEGIBLE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Bill Mathis

Address Box 32

Midland, Texas

By Bill Mathis

Title _____