



(SUBMIT IN TRIPLICATE)
OCT 22 10 18 AM '63
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Lease No. **034667**
Unit **Gregory-Federal-El Paso**

OCT 17 1963

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 15, 19**63**

Well No. **1** is located **660** ft. from **SE** line and **1630** ft. from **E** line of sec. **33**
SW/4 SE/4 Sec. 33 23-S 37-E N.M.P.M.
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Crosby Devonian Lea New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3010** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD 8461'. Set 5-1/2" OD 20 & 23# P-110 & N-80 casing @ 8460.76' with BV collar @ 7487'. Cemented around shoe w/145 sacks and thru BV collar with 494 sacks. Cement did not circulate. Ran temperature survey, top of cement 3430' from surface. WOC 24 hrs. Pressured casing to 1500# for 30 mins, no decrease in pressure.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Union Texas Petroleum Corporation**

Address **Box 1839**

Midland, Texas

By

Title **District Clerk**