



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Form Approved.

Land Office **Las Cruces**

Lease No. **034667**

U.S. Geological Survey Federal -
El Paso

AUG 26 1963

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	XX
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 22, 19**63**

Well No. **1** is located **660** ft. from **XX** line and **1650** ft. from **E** line of sec. **33**

SW4 SE4 Sec 33

($\frac{1}{4}$ Sec. and Sec. No.)

25-S 37-E

(Twp.)

(Range)

NMPM

(Meridian)

Crosby Devonian

(Field)

Lea

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is **3010** ft. **Est.**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**Drilled 17-1/2" hole to 620'. Ran 13-3/8" OD 48# casing
set @ 516'. Cemented w/450 sacks cement. Cement
circulated. WOC 24 hrs. Tested csg to 1300# for 15 mins.
No decrease in pressure.**

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Union Texas Petroleum Corporation**

Address **Box 1859**

Midland, Texas

By

Title **District Clerk**