



APPROVED

(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

J. L. GORDON
ACTING DISTRICT ENGINEER

Budget Bureau No. 42-R358.4.
Form Approved.

Land Office Las Cruces

Lease No. 032511-F

Unit Stuart

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 2, 1963

Well No. _____ is located 150 ft. from N line and 150 ft. from W line of sec. _____

14 14 25-3 37-2 NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

N. Justice (Twp-Drink) Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3125 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD 1036'. Set 9 5/8", 32# H-40 casing 1036' w/546 sacks cement. Cement circulated. WOC 24 hrs. Tested casing to 1000# for 30 mins, no decrease in pressure.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Union Texas Petroleum Corporation

Address P. O. Box 1059

Midland, Texas

By [Signature]

Title District Clerk