Form 9-331 (May 1963)		(i)ther instructions of	buoget bureau No. 42-R1424.
DEPARTMENT UP THE INTERIOR Verse side) GEOLOGICAL SURVEY			5. LEASE DESIGNATION AND SERIAL NO. NM-03429-A
	6. IF INDIAN, ALLOTTEE OR TRIEF NAME		
	NOTICES AND REP or proposals to drill or to deeper APPLICATION FOR PERMIT-"	ORTS ON WELLS n or plug back to a different reservoir. for such proposals.)	
1. OIL GAS WELL XX (THER		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR			8. FARM OR LEASE NAME
Skelly Oil Company			West Jal Unit
	dland Towar 70701		9. WELL NO.
P. O. BOX 1351, Mi. 4. LOCATION OF WELL (Report 14	ocation clearly and in accordance	e with any State requirements.*	10. FIELD AND POOL, OR WILDCAT
See also space 17 below.) At surface	Undesignated Fusselman		
1980' FNL and 660'	FEL Sec. 20-255-36	E Constant and a second	11. SFC., T., R., M., OR BLK. AND SURVEY OR ALFA
14. FERMIT NO.	15. ELEVATIONS (Show	whether DF, RT, GR, etc.)	Sec. 20-25S-36E 12. COUNTY OR PARISH 13. STATE
		3076' GR	Lea New Mexico
16. Ch	I. A		
Check Appropriate box to indicate ratifie of Nonce, Report, of C			or Under Data BSEQUENT REPORT OF:
TEST WATER SHUT-OFF	FULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT		FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other)et 3-1/2	liner, perf. & treat x sults of multiple completion on Well
17. DESCRIPE PEOPOSED OR COMPL	ETED OPERATIONS (Clearly state as directionally drilled, give subst	Il pertinent details and give pertinent d	completion Report and Log form.) ates, including estimated date of starting any ertical depths for all markers and zones perti-
Laterolog 15,3 and Formation 2) Ran 71 jts. (2 and set with T 5-1/2" liner i liner hanger p two collars pa is at 17,082-1	92-17,071'; Continu Density Log 15,392- 114') of 3-1/2" OD IW Type "L" Liner h s at 14,967' and bo acker assembly 14,9 inted with radioact 7,084'; float colla	17,069'. 10.2# N-80 Hydril FJ R-2 anger from 14,930-17,084 ttom at 17,084'. Liner 30-14,936'; packer bore ive material at 16,182' r 17,051-17,052'; float	76'; Compensated Neutron Condition "A" Liner '. Top of liner inside hanger is at 14,936-14,941'; receptacle 14,941-14,967'; and 16,271'; guide shoe landing collar 17,020-17,021
3) Cemented liner with 250 sacks of Class "H" cement containing 4/10ths of 1% CFR-2, 1% Halad 9 and 1/4# Flocele per sack. Pumped plug to 17,020'. Reversed out 60 sacks.			
4) Ran Gamma Ray Collar Log 17,020-15,350'.			
		(14,940') of 2-7/8" OD 7 ead with TIW packer seal	.9# N-80 Condition "A" assembly stinger and set
•	seal assembly and t	ubing with 6000# for 30	minutes: held okav.
7) Perforated wit 16,520', 16,53	h one .33" hole at: 7', 16,550', 16,565	16,449', 16,475', 16,4 ', 16,576', 16,591', 16,	81', 16,484', 16,508',
18. I hereby certify that the for	and the tens and correct	(Continued on Page	2)
SIGNED (Eight	<u></u>	rLELead_Clerk	Dec. 19, 1972
(This space for Federal or S	State office use)	ACCEPTED FOR	RECORD
APPROVED BT CONDITIONS OF APPROVA	L, IF ANY:	ACCEPTED FOR	1972 RA

1

- -----

*See Instructions on Revence Side GEOLOGICAL SURVEY HOBBS, NEW MEXICO