

1-R.J. STARRAK-TULSA
1-A.B. CARY-MIDLAND
1-ELB, UNNED-STAT1-FILE
1-BH, FIELD CLERKForm Approved.
Budget Bureau No. 42-R1424DEPARTMENT OF THE INTERIOR COPY TO
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐
well well other2. NAME OF OPERATOR
Getty Oil Company3. ADDRESS OF OPERATOR
P. O. Box 730, Hobbs, New Mexico 882404. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: Unit letter K, 1650' FSL & 1650' FWT
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐☐
☐
☐
☐
☐
☐
☐
☐

(other) Placed on pump

X

RECEIVED

JAN 5 1979

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1-9-78 - Rigged up pulling unit. Killed well with 50-50 brine water. Unset TIW pkr. Laid down sliding sleeve and pkr. with hydraulic hold down.

1-10-78 - Tested tbq. in hole. Set tbq. at 5470'. Ran 2" x 1 1/4" x 20' RHBC pump.

1-11-78 - Placed well on production (well ceased flowing; swabbing unsuccessful-placed on pump).

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Dale R. Crockett TITLE Area Supt. DATE 1-4-79

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY: