

COPIES RECEIVED	
TRIBUTION	
FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-85

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
K-4565

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Union Texas Petroleum Corporation	8. Farm or Lease Name Crawford State
3. Address of Operator 1300 Wilco Building, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER North 660 FEET FROM THE South LINE AND 2,209 FEET FROM THE West LINE, SECTION 4 TOWNSHIP 24-S RANGE 38-E NMEM.	10. Field and Pool, or Wildcat Stateline (Ellen.)
15. Elevation (Show whether DF, RT, GR, etc.) 3,279' DF or 3,266' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIATION WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- December 11, 1975, re-entered well and pulled 2-3/8" tubing and packer.
- Set CIBP @ 12,030' and spotted 35' of cement to 11,995'.
- Ran free point indicator and cut 5 1/2" casing @ 8,790'.
- Pumped brine into hole (circulated), and pulled 224 joints 5 1/2" casing.
- Ran tubing into top of cut off casing and circulated hole with 10#/gal. Brine Gel Mud.
- Spotted 55 sx. plug from 7,510' to 7,310'.
- Spotted 50 sx. plug from 5,631' to 5,531'.
- Spotted 50 sx. plug from 4,460' to 4,360'.
- Spotted 100 sx. plug from 3,330' to 3,130'.
- Pulled tubing. Removed casing head and spotted 10 sx. cement plug at surface.
- Welded 1/2" plate on 13-3/8" casing and installed dry hole marker.
- Completed plugging well December 20, 1975.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Stanley A. Post TITLE Gas Measurement Analyst DATE December 23, 1975
APPROVED BY John W. Runyan TITLE Geol. DATE 1975
CONDITIONS OF APPROVAL, IF ANY: