

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION OFFICE O. G. B.

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

MAR 30 1 03 PM '66

Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
K3091

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER - Dry - Plugged & Abandoned	7. Unit Agreement Name
2. Name of Operator PAULEY PETROLEUM INC.	8. Farm or Lease Name New Mexico State
3. Address of Operator 930 Petroleum Life Building, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM West LINE, SECTION 36 TOWNSHIP 25 RANGE 34 NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3305.4' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well plugged and abandoned in accordance with New Mexico Oil Conservation Commission specifications, March 17, 1966.

March 17, 1966 - Total depth 5795'.

Cement plugs for abandonment were placed as follows:

- 10 sacks plug at surface**
- 50 sacks plug from 831' to 1090'**
- 35 sacks plug from 5261' to 5450'**
- 25 sacks plug from 5660' to 5795'**

Displaced all cement with mud.

Installed required well marker.

Note: Approximate date for final well site inspection is April 13, 1966.

(Note: Discussed the plugging and abandonment procedures and received verbal permission to plug and abandon well from New Mexico Oil Conservation Commission District Office, Hobbs, New Mexico, on March 16, 1966.)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. C. Hammer TITLE Agent DATE March 23, 1966

APPROVED BY Leslie A. Clements TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: