

PROPERTY OF NEW MEXICO OIL CONSERVATION COMMISSION
PROPERTY OF
NAME
FILE
U.S. STATE
LAND OFFICE
OFFICIAL

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes C-101
C-102 and C-103
Effective 1-1-55

COMPLETION OF WELL AND PRODUCTION RECORDS

DATE OF COMPLETION: 11-14-60

WELL NAME: San Juan Company

ADDRESS: P. O. Box 7067, El Paso, Texas 79704

WELL LOCATION: 11-956 south 330 West 12 25-S 37-E

WELL DEPTH: 3111' OR

DATE OF LEASE: 1-1-55

TYPE OF LEASE: ☒ State ☐ Federal

NAME OF LESSEE: S. W. Eakin

ADDRESS: 81

WELL NAME: 11-956 south 330 West 12 25-S 37-E

WELL DEPTH: 3111' OR

Check Appropriate Box To Indicate Nature of Needed Report or Other Data

NO. OF INTENTION TO: ☐ NO. OF INTENTION TO: ☐

PRODUCTION RECORDS	PRODUCTION RECORDS	PRODUCTION RECORDS	PRODUCTION RECORDS
PRODUCTION RECORDS	PRODUCTION RECORDS	PRODUCTION RECORDS	PRODUCTION RECORDS
PRODUCTION RECORDS	PRODUCTION RECORDS	PRODUCTION RECORDS	PRODUCTION RECORDS
PRODUCTION RECORDS	PRODUCTION RECORDS	PRODUCTION RECORDS	PRODUCTION RECORDS

TO BE FILLED IN BY THE OPERATOR OF THE WELL. (If the well is not producing, fill in the space for the name of the operator of the well.)

- 11-14-60 HIRSHU. Pump was stuck. Jarred on pump, failed to unset. Back rods off. Rec. 100 3/4" rods and 41 5/8" rods. SDOW.
- 11-15-60 Killed well. Installed 30' POH w/60 jts. 2 1/16" tbg. Well came in flowing. P/75 blks. broke down annulus. POH w/32 jts. 2 1/16" tbg. Back rods off. POH w/60 rods and fishing hook from pump.
- 11-16-60 POH w/60 jts. 2 1/16" tbg. SN, perf. PA tbg. Anchor. Install HOP on long string.
- 11-18-60 OSH w/lapersion block on 2 1/16" tbg. Found 5/8" hole break looking up. OSH w/O.S. on rod string. Caught off on POH w/rods and pump.
- 11-19-60 Killed well. Attempted to release on-off tool. Could not release.
- 11-20-60 Released on-off tool. Pulled 183 jts. 2 1/16" tbg. and on-off tool. Lay down and tally tbg. PO and OSH w/32 jts. 2 3/8" tbg and on-off tool.
- 11-21-60 Killed well. Pulled 184 jts. 2 3/8" tbg w/en-off tool. Tagged plug at 3111'. Unable to latch on w/en-off tool. P/75 blks. broke down annulus and got stuck down. Latched on w/en-off tool. Worked plug 5 1/2 hrs. Could not release. (See back)

- 11-22-80 Ran overshot to pull pkr. Killed well, G/H w/jars and tbg., latched on to on-off tool. Jarred pkr 5' up hole and knocked on-off tool lugs loose. POH w/tbg. and jars.
- 11-23-80 G/H w/overshot, bumper sub and hyd jars. Latched on to fish, jarred 8 times. POH w/tbg., rec. on-off tool and pair of sliding sleeve.
- 11-25-80 G/H w/overshot to catch sliding sleeve but could not catch fish. POH w/tbg and tools. G/H w/O.S. jars. Bumper sub and tbg. Caught fish jars 30 mins. Could not jar free. Set 50,000 on slip. SDCR.
- 11-27-80 Jarred on pkr could not jar free. Cut off fish w/O.S. and POH w/tbg and tools. Left G/H w/O.S. jars. Bumper sub and tbg. Tag fish. Spot 15% HCl acid w/double iron inhibitor over fish. Let soak 45 mins. to dissolve scale. Attempt to catch fish. Could not catch fish. Put w/2x3 jts. tbg.
- 11-29-80 G/H w/wireline 2 3/8" log preparing to mill out. Tag fish unable to get over collar. POH w/tbg and tools. G/H w/2 1/2" mill, 10' barrel, 8-3 1/8 bits and 2 tbg.
- 11-30-80 Ran 5100' 2 3/8" tbg, 2 1/2" mill, 10' wash over line and DC's. Tagged pkr at 5700'. Impd 350 RW, unable to circ. Milled 7 1/2 hrs., cut approx. 10" w/no circ.
- 12-1-80 Milling pkr this AM.
- 12-2-80 Running new mill. Mill 4 hrs. POH w/tbg., 8-3 1/2" DC and mill. Change cut mill. G/H w/2 1/2" mill 3-3 1/2" DC and 175 jts. 2 3/8". Left swinging overnight.
- 12-3-80 Milled 7 1/2 hrs. Milled 26 inches.
- 12-4-80 Killed on pkr 7 1/2 hrs. Milled 13". POH w/tbg and mill. SDCR.
- 12-5-80 POH w/DC's. Left 1 jt. of washover pipe and mill. Ran tapered tap on tbg. Could not catch fish. POH w/tbg and tbg. Ran Imp block. Showed wash pipe split.
- 12-6-80 Milled 2' of wash pipe. POH. POH w/tbg and spoon. Caught wash pipe and mill. Set w/fish.
- 12-7-80 Ran impression block and magnet. No luck on top of fish. Ran overshot, bumper sub, jars on tbg. Caught fish. Jarred on fish. Could not jar free.
- 12-8-80 Ran COI and free bc. Found tbg free on etc. Top stuck at 5725'. Ran string shot over free collar at 5724'. Could not free collar. POH w/wireline.
- 12-10-80 G/H w/string shot. Failed to fire. POH w/string shot. G/H w/string shot. String shot fired. POH w/tbg., jars, DC's, bumper sub and top of extension. Left top of extension and overshot in hole (122').
- 12-11-80 Ran impression block. G/H w/2 3/8" extension and tbg. Latched on to fish.
- 12-12-80 G/H w/2 7/8" impression block. POH could not get through sliding sleeve fishing rack. POH w/tbg. POH w/string shot. G/H w/string shot. Shot collar off pkr barrel. POH w/tbg and pkr barrel.
- 12-13-80 Ran 3-3/4" cone-shaped impression block. Jarred 3 1/2" ring around block. POH and G/H w/2 1/4" spoon. Caught fish. Pulled gyrate off. POH w/tbg and spoon. SDCR.
- 12-14-80 G/H w/2 3/4" tbg and tbg at top. Caught fish. POH w/tbg extension bowl and overshot. Left w/2 3/4" tbg and tbg.