

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved
Bureau Order No. 42 R1104

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

LC-032326 b

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

MAFPU

8. FARM OR LEASE NAME

Jack B-27

9. WELL NO.

3

10. FIELD AND LOG, OR WILDCAT

JUSTIS BLINCKEY

11. SEC., T., R., N., OR E. AND SURVEY OR AREA

Sec 27, T-24S, R-37E

12. COUNTY OR PARISH

Tex

13. STATE

N. Mex.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Continental Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 460, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980' FSL 4330' FEL of Sec. 27, T-24S, R-37E,

In Dea County, N. Mex.

14. PERMIT NO.

15. ELEVATIONS (Show whether DZ, EL, GR, etc.)

3200' DF EST.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☒
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was spudded at 5 PM on 10-17-69.
Drilled 12 1/4" hole and set 8 5/8" 24 # casing at 984'.
Cemented with 4.40 sacks of class C cement. Circulated cement and waited on cement 24 hrs. Tested casing with 1000 # for 30 minutes, held OK.

18. I hereby certify that the foregoing is true and correct

SIGNED

M. E. Yeakley

TITLE Adm. Section Chief

DATE 10-20-69

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

[Signature]

District Engineer

USGS-5 FILE

Per Am. Wells 2

Drilled 2

Chen 2

*See Instructions on Reverse Side

OCT 22 1969