| Form .9-331<br>(May 1963)  | لاً<br>TED STATES کی TEPARTM   |   | re- B  | orm approved.<br>udget Bureau No. 42-R1424<br>ESIGNATION AND SEBIAL NO.     |
|--|--|---|--|---|
| -  | GEOLOGICAL SURVEY  |   | LC-03  |   |
|  | RY NOTICES AND REPORT  | 'S ON WELLS   |  | N, ALLOTTEE OR TRIBE NAME   |
|  | m for proposals to drill or to deepen or p<br>lse "APPLICATION FOR PERMIT" for su  | uch proposals.)                                     |  |   |
| 1.<br>OIL CAS<br>WELL WELL   | OTHER  |   | -  | REEMENT NAME  |
| 2. NAME OF OPERATOR  |  |   |  | Fristoe 'B'   |
| 3. ADDRESS OF OPERATOR   |  | ······································              | 9. WELL NO   |   |
| P. O. Box 728<br>4. LOCATION OF WELL (Repo<br>See also space 17 below. | Hobbs, New Mexico 882  | 240<br>any State requirements.*                     | 14<br>10. FIBLD A  | AND POOL, OR WILDCAT  |
| At surface Well is the East  | located 660' from the Nor<br>Line of Section 35, T-2 <sup>1</sup><br>a County, New Mexico  | rth Line and 2310' fro<br>+-S, R-37-E, Unit Lett    | m <u>Undesi</u><br>ter <sup>11. SEC. T.<br/>Sec. 3<br/>Unit Le</sup> | ignated<br>"E. M. OF BLK. AND<br>FY OR ABLA<br>5, T-24-S, R-37-E<br>etter B |
| 14. PERMIT NO.   | 15. ELEVATIONS (Show wheth   | er DF, RT, GR, etc.)                                | 12. COUNTY   | OR PARISH 18. STATE   |
| Regular  | 3183' (DF)   |   | Lea  | New Mexic   |
| 16.  | Check Appropriate Box To Indicat   | te Nature of Notice, Report, o                      | or Other Data  |   |
| NOT  | ICE OF INTENTION TO :  | SUBS  | SEQUENT REPORT   | OF :  |
| TEST WATER SHUT-OFF  | PULL OR ALTER CASING   | WATER SHUT-OFF                                      | x  | REPAIRING WOLL  |
| FRACTURE TREAT   | MULTIPLE COMPLETE  | FRACTURE TREATMENT                                  |  | ALTEBING CASING   |
| SHOOT OR ACIDIZE   | ABANDON*   | SHOOTING OR ACIDIZING                               | L  | ABANDONMENT*  |
| REPAIR WELL<br>(Other)   | CHANGE PLANS   | (Other)<br>(Note: Report rest<br>Completion or Reco | ults of multiple   | completion on Well  |
| 5800' w/520 sx.  | TOTAL DEPTH<br>8 5/8" O. D. 20# Smls.<br>oints) 4 $\frac{1}{2}$ " O.D. 10.50#<br>TLW Cement w/5# gilsonit<br>lete 10:45 A. M., April 1 | K-55 Smls. Casing and<br>te per sack. Cement C      | d Cemented   | @<br>Plug @   |
| Tested 42" 0.D.<br>April 15, 1970.                                     | Casing w/1500# for 30 min<br>Tested 0. K   | utes from 2:30 P. M.                                | to 3:00 P.   | M.,   |
|  |  |   |  | •   |
| Job Complete 3:0   | 0 P. M., April 15, 1970.   |   |  |   |
|  |  |   |  |   |
|  |  |   |  |   |
|  |  |   |  |   |
|  |  |   |  |   |
|  |  |   |  |   |
| 18. I hereby certify that the  | foregoing is true and correct  | Assistant District                                  | ······   | •   |
| SIGNED JUL   |  | Superintendent                                      | DATE   | April 17, 1970  |
| (This space for Federal  | or State office use)   |   |  | <del></del> 7   |
|  |  |   | FOD DIRD   | RD-   |
| APPROVED BY<br>CONDITIONS OF APPR                                      | OVAL, IF ANY :   | <del>مذمل بن في تري بري ب</del> ي                   |  |   |
|  |  | -<br>Aps  | 2 0 1970   |   |
|  | *Č I · ·   |   |  | VEY   |
|  | "See Instruct  | ions on Reverse Side 3, 9201.<br>HOBBS,             | NEW MEXIC  | o   |

ł





## APR 2 8 1970

CHL COMPENSATION CORM.