INCLINATION REPORT

 313 E. Anderson Lane - Suite #332

 OPERATOR JOHN H. HILL
 ADDRESS Austin, Texas 78752

 LEASE Judy
 WELL NO. 1 FIELD Langlie Mattix

LOCATION NE/4 of NW/4, Section 7, T-25S, R-37E, Lea Co., New Mexico

Depth	Angle of Inclination (degrees)	Displacement/ 100'	Accumulated Displacement
182	1/4	0.44	. 0.80
340	1/4	0.44	1.50
828	1/2	0.87	5.75
1115	1/2	0.87	8.25
1603	3/4	1.31	14.64
1957	1	1.75	20.84
2468	1 - 1/4	2.18	31.98
2967	1	1.75	40.71
3621	1-1/4	2.18	54.97

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

By: Title: Superintendent

Affidavit:

Before me, the undersigned authority, appeared <u>V. Leon Wiederkehr</u> known to me to be the person whose name is subscribed herebelow, who, on making deposition, under oath states that he is acting for and in behalf of the operator of the well identified above, and that to the best of his knowledge and belief such well was not intentionally deviated from the true vertical whatsoever.

My Commission expires (Affiant's Signature)

Sworn and subscribed to in my presence on this the 27 day of March

_____, 19<u>74</u>___

Notary Public in and for the County of

Seal