

INCLINATION REPORT

OPERATOR Union Texas Petroleum ADDRESS 1300 Wilco Bldg, Midland, Texas
 LEASE Langlie Jal Unit WELL NO. 60 FIELD Langlie-Mattix (Queen) 79701
 LOCATION T-24S, R-37E, Lea County, New Mexico

Depth	Angle (Inclination 'degrees)	Displacement	Displacement Accumulated
300	1/4	1.3200	1.3200
815	3/4	6.7465	8.0665
1300	3/4	6.3535	14.4200
1788	1	8.5400	22.9600
2223	1 1/4	9.4830	32.4430
2717	1 1/2	12.9428	45.3858
3072	1 1/4	7.7390	53.1248
3460	1 1/4	8.4584	61.5832
3850	1	6.8250	68.4082

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Cactus Drilling Company

By: Ken Hedrick
 Title: Ken Hedrick, Drlg. Supt.

Affidavit:

Before me, the undersigned authority, appeared Ken Hedrick known to me to be the person whose name is subscribed herebelow, who, on making deposition, under oath states that he is acting for and in behalf of the operator of the well identified above, and that to the best of his knowledge and belief such well was not intentionally deviated from the true vertical whatsoever.

Ken Hedrick
 (Affiant's Signature)

Sworn and subscribed to in my presence on this the 27th day of December 19 74

MY COMMISSION EXPIRES 3-1-76

James X. Murphy
 Notary Public in and for the County
 of Lea, State of New Mexico