

INCLINATION REPORT

OPERATOR Union Texas Petroleum ADDRESS 1300 Wilco Bldg, Midland, Tex 79701

LEASE Langlie Jal Unit WELL NO. 76 FIELD Langlie-Mattix (Queen)

Section 9

LOCATION T-24S, R-37E, Lea County, New Mexico (1980' FNL & 660' FWL)

Depth	Angle (Inclination degrees)	Displacement	Displacement Accumulated
443	1/4	1.9492	1.9492
805	3/4	4.7422	6.6914
1584	1/2	6.7773	13.4687
1994	1/2	3.5670	17.0357
2487	1 1/4	10.7474	27.7831
2635	1 1/4	3.2264	31.0095
3050	2	14.4835	45.4930
3525	1 3/4	14.4875	59.9805
3664	1 3/4	4.2395	64.2200
3850	3/4	2.4366	66.6566

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Cactus Drilling Company

By: Ken Hedrick
Title: Drilling Superintendent

Affidavit:

Before me, the undersigned authority, appeared Ken Hedrick known to me to be the person whose name is subscribed herebelow, who, on making deposition, under oath states that he is acting for and in behalf of the operator of the well identified above, and that to the best of his knowledge and belief such well was not intentionally deviated from the true vertical whatsoever.

Ken Hedrick
(Affiant's Signature)

Sworn and subscribed to in my presence on this the 27th day of _____

November 1974

MY COMMISSION EXPIRES 3-1-76

Jerry L. Dwyer
Notary Public in and for the County
of Lea, State of New Mexico

Seal