

INCLINOMETER REPORT

OPERATOR Union Texas Petroleum ADDRESS 1300 Wilco Bldg. Midland, Tex 79701
 LEASE Langlie Jal Unit WELL NO. 91 FIELD Langlie-Mattix (Queen)
 LOCATION T-24S, R-37E, Lea County, New Mexico

Depth	Angle (Inclination 'degrees)	Displacement	Displacement Accumulated
479	1/4	2.1076	2.1076
1006	1/2	4.5849	6.6925
1479	1	8.2775	14.9700
1954	1 1/4	10.3550	25.3250
2425	1 1/2	12.3402	37.6652
2520	1 1/2	2.4890	40.1542
2865	1	6.0375	46.1917
3219	1 1/4	7.7172	53.9089
3690	1 1/4	10.2678	64.1767
3850	1	2.8000	66.9767

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Cactus Drilling Company
 By: Ken Hedrick
 Title: Drilling Superintendent

Affidavit:

Before me, the undersigned authority, appeared Ken Hedrick known to me to be the person whose name is subscribed herebelow, who, on making deposition, under oath states that he is acting for and in behalf of the operator of the well identified above, and that to the best of his knowledge and belief such well was not intentionally deviated from the true vertical whatsoever.

Ken Hedrick
 (Affiant's Signature)

Sworn and subscribed to in my presence on this the 27th day of November 19 74

MY COMMISSION EXPIRES 3-1-76

Jerry L. Myrick
 Notary Public in and for the County
 of Lea, State of New Mexico

Seal