

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator <u>Burleson &amp; Huff</u>		8. Farm or Lease Name <u>Arco-Lanehart</u>
3. Address of Operator <u>P. O. Box 935, Midland, Texas 79701</u>		9. Well No. <u>1 2</u>
4. Location of Well UNIT LETTER <u>H</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>21</u> TOWNSHIP <u>25 - S</u> RANGE <u>37-E</u> NMPM.		10. Field and Pool, or Wildcat <u>Langlie-Mattix</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3077.6 GR</u>		12. County <u>Lea</u>

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

#### NOTICE OF INTENTION TO:

#### SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

### 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set 949' of 8-5/8" casing @ 949' with 200 sx of light cement and 150 sx Class C Cement. Circulated 30 sx on ground. Waited on Cement 12 hours. Tested casing to 1000#. Found cavern in base of Anhydrite @ 1056'. Lost all returns. Cemented with 350 sx, could not get returns. Dry drilled to 1250'. Moved off of hole. Prep to junk and abandon. We will file abandon plans on this well at a later date. Plan to drill #2-Y as a replacement hole.

Expires 12/1/76

### 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Co-Owner</u>	DATE <u>11-14-75</u>
---------------------------	-----------------------	----------------------

APPROVED BY <u>[Signature]</u>	TITLE <u></u>	DATE <u>11-14-75</u>
--------------------------------	---------------	----------------------

CONDITIONS OF APPROVAL, IF ANY: