

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM 14629
2. NAME OF OPERATOR Union Texas Petroleum corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 1300 Wilco Building, Midland, Texas 79701		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330' FNL & 1650' FWL		8. FARM OR LEASE NAME Stuart
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3174.2' GL	9. WELL NO. 1
		10. FIELD AND POOL, OR WILDCAT Langlie-Mattix
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 9, T-25-S, R-37-E
		12. COUNTY OR PARISH Lea
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) Csg. Test & Cementing <input checked="" type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. Spudded 12 $\frac{1}{4}$ " hole @ 4 P.M., 9-7-77.
2. September 8, 1977, TD of 12 $\frac{1}{4}$ " hole was 782'. Set 782' of 8 5/8" 24# K-55 casing & cemented w/430 sx. Class "C" w/2% CaCl. (Cmt. circ.) After WOC 9 $\frac{1}{4}$ hrs. drilled out excess cement and tested casing to 750# w/no dec. in press.
3. September 14, 1977, TD 3739'. Set 5 $\frac{1}{2}$ " K-55 14# csg. @ 3738' and cemented w/550 sx. Class "C" 3% Lo-Dense w/1/4# Cello & 6# salt/sk followed by 200 sx. Class "C" w/5# salt/sk. Circ. 30 sx. cement.
4. At the present time, we are waiting on a completion unit to complete this well.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Sr. Prod. Analyst

DATE

9-16-77

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
SEP 21 1977

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

*See Instructions on Reverse Side