APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

COPY TO O. S. S.

Form Approved.

UNITED STES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY				Budget Bur	reau No. 42-R1424
			5. LEASE	10105	
			NM 10195 6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
			O. IF INDIAN, AL	LOTTEE OR 1	TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)			7. UNIT AGREEM	AENT NAME	
				esignated	
			8. FARM OR LEA	SF NAME	<u> </u>
1. oil gas uther			Little Ha	wk Feder:	al
2. NAME OF OPERATOR			9. WELL NO.		
Gifford, Mitchell & Wisenbaker			1		<u>.</u>
3. ADDRESS OF OPERATOR			10. FIELD OR WILDCAT NAME		
			Sioux	x Yates	
1280 MNB TWR., Midland, Texas 79701 4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17			11. SEC., T., R., N AREA	L, OR BLK. A	AND SURVEY OF
Delow.)			Sec. 33, T25S, R36E		
AT SURFACE: 1980'FNL and 660' FWL of Sec. AT TOP PROD. INTERVAL: AT TOTAL DEPTH:			12. COUNTY OR F	1233, R3	36E
			Lea	ARISH 13.	STATE
			14. API NO.	INEW	Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA					
MEI ONI, ON OTHER	DATA		15. ELEVATIONS	(SHOW DF.	KDB AND WO
REQUEST FOR APPROVAL	TO: SUBSEQUENT RE	PORT OF	3022GR		TOP WAY AND
TEST WATER SHUT-OFF			4.7		1174
FRACTURE TREAT			*		
SHOOT OR ACIDIZE REPAIR WELL					그렇게 살다.
PULL OR ALTER CASING	H		TNOTE! Report tesu	its of multiple (completion or zone
MULTIPLE COMPLETE	H H	11.33	cualife off t	Form 9–330.)	Ser S
CHANGE ZONES			16 (3)		
ABANDON* (other)					
			FIGE FURVEY	A	
17. DESCRIBE PROPOSED	OR COMPLETED OPERATIONS te of starting any proposed wo	Clearly state		1	
including estimated da measured and true vert	te of starting any proposed wo tical depths for all markers and	rk. If well is di	rectionally drilled, gi	s, and give p ve subsurfac	pertinent dates,
	near departs for air markers and	zones pertinent	t to this work.)*		is callotts and
			5		
9/25/80 -	+ 26001 -+41-	450			
-,,	set 5 1/2", 14#, K-5 sacks Class C cement	with 28 C	ac 2030 WIEU	450,	
	per sack, mixed at]	4.2 ppg	Wait on comon	TE .	
	11 days. Tested cas	sing at 110	00 psi for 30		
	minutes. Held OK.		o Par for 50		
			의 (1) 전 10 년 :		
			ैं : दें : :		, 말충분분
			44		
			, in the second	공급을 무취하	
Subsurface Safety Valve: Ma					
18. I hereby certify that the foregoing is true and correct				_ Set @	Ft.
$\mathcal{Q} \mathcal{P}$					
SIGNED A. B. V	TITLE Proc	L_Engineer	DATE	/13/80	
					~~~~~~

*See Instructions on Reverse Side

(This space for Federal or State office use)

ACCEPTED FOR RECORD

OCT 2 1 1980

U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO