

INCLINATION REPORT

OPERATOR Maralo Inc. ADDRESS Box 832, Midland, Texas 79702
 LEASE NAME Jalmat Yates Unit # 14 WELL NO. 14 FIELD
 LOCATION 1100' FNL, 2530' FEL, Sec. 13, T 25S, R 36E

DEPTH	ANGLE INCLINATION DEGREES	DISPLACEMENT	DISPLACEMENT ACCUMULATED
423	3/4	5.5413	5.5413
783	3/4	4.7160	10.2573
1278	1	8.6625	18.9198
1685	1 3/4	12.4135	31.3333
2203	2	18.0782	49.4115
2668	2	16.2285	65.6400
3156	1 3/4	14.8840	80.5240
3525	1 1/2	9.6678	90.1918

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

CACTUS DRILLING COMPANY

Rhonda Ford
 TITLE Rhonda Ford, Office Manager


AFFIDAVIT:

Before me, the undersigned authority, appeared Rhonda Ford
 known to me to be the person whose name is subscribed herebelow, who, on making
 deposition, under oath states that he is acting for and in behalf of the operator
 of the well identified above, and that to the best of his knowledge and belief such
 well was not intentionally deviated from the true vertical whatsoever.

Rhonda Ford
 AFFIANT'S SIGNATURE

Sworn and subscribed to in my presence on this the 10th day of September, 1980

SEAL



Notary Public in and for the County
 of Lea, State of New Mexico

RECEIVED

FEB 27 1981

U.S. DEPARTMENT OF JUSTICE

[Handwritten signature]