Form 9-331 Dec. 1973 Form Approved. Budget Bureau No. 42-R1424

> (/b) R TRIBE NAME

UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE <i>LC-032581</i>			
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR			
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME NMFU			
not use this form for proposals to drill or to deepen or plug back to a different ervoir. Use Form 9–331–C for such proposals.	8. FARM OR LEASE NAME Sholes B-19 Co			

_			0.00000	e to drill or	TO THE PROPERTY OF THE	JO DACK TO A C	nnerenci					
DO ese	rvoir. Use F	orm 9–331	C for su	ich proposal			写话	₹ 8.		LEASE NAM		
•	-:1	726			1111111111			_ ال	Shole	s B-19	Com	
1.	oil	gas well		other	AHO	400		9.	WELL NO.			
2	NAME O	F OPERA	ATOR	,	AUG	5 130				7		
	CONOC					0 00	-	10.	FIELD OR	WILDCAT N	AME	
_	100050	C OF OF	CDATO	R	TU.S. GEO	LOGICAL	SURV	ZYnd	esionatec	Devonia	n E Ellen	urger
٥.	P. O. Bo	x 460. 1	Hobbs.	N.M. 88	240 HOBB	,自己生活	ICO	11.	SEC., T., F	R., M., OR B	LK. AND SU	RVEÝ OF
_	LOCATIO	N OF W	FII (RE	PORT LOC	CATION CLEAF	RLY. See Sp.	ace 17		AREA			
	6 -1					(2). 000 0		5	ec. 19.	T-255	, R- 37E	
AT SURFACE: 1980 FSL E 1980 FWL AT TOP PROD. INTERVAL:						12.	COUNTY	OR PARISH	13. STATE			
	AT TOP	PROD.	INTERV	AL:			:		Lea		NM	
	AT TOT	L DEPTI	1 :					14.	API NO.	i	·····	
								i				

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

15. ELEVATIONS (SHOW DF, KDB, AND WD)

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
PULL OR ALTER CASING
MULTIPLE COMPLETE
CHANGE ZONES
ABANDON*

SUBSEQUENT REPORT OF:

SUBSEQUENT REPORT OF:

AUDITOR OF TREPORT OF:

TORROW OF TREPORT OF:

TOR

(other) TI) and production csq

usgs s NMFU5 (NOTE: Report results of multiple completion or zone change on Form 9–330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Reached TD of 13,500' on 7/26/81. Ran 7", 29#, C-75 & L-80 buttress csg. set at 13,500'. Contdin 2 stages: Ist stage: 727sx Class Hent.

2nd stage: 776sx Class H life, tail w/ 470sx Class H. Did not circulate cont. Toc to be determined when completion activities begin.

Subsurface Safety Valve: Manu. and Type	Set @	Ft.
18 I have by postify that the foregoing is true an	and correct	01
ACCEPTED FOR RECORD 7	TITLE Administrative Supervisor DATE August 3, 19,	
APPROVED BY	_ TITLE DATE	
CONDITIONS OF ARROYAL, 7 1981		
U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO	*See Instructions on Reverse Side	