

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

| | | |
|------------------------|--|--|
| NO. OF COPIES RECEIVED | | |
| DISTRIBUTION | | |
| SANTA FE | | |
| FILE | | |
| U.S.G.S. | | |
| LAND OFFICE | | |
| OPERATOR | | |

5a. Indicate Type of Lease
State ☒ For ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|--|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator Gulf Oil Corporation | 8. Farm or Lease Name Arnott-Ramsay (NCT-B) |
| 3. Address of Operator P. O. Box 670, Hobbs, NM 88240 | 9. Well No. 12 |
| 4. Location of Well UNIT LETTER 0 500 FEET FROM THE South LINE AND 1480 FEET FROM THE East LINE, SECTION 32 TOWNSHIP 25S RANGE 37E NMPM. | 10. Field and Pool, or Wildcat Langlie Mattix |
| 15. Elevation (Show whether DF, RT, GR, etc.) 2988.4' GL | 12. County Lea |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

| NOTICE OF INTENTION TO: | | SUBSEQUENT REPORT OF: | |
|--|---|---|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/> | OTHER <input type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Cactus spudded 12½" hole @ 9P 1-13-82. TD 7A, 1-14-82. RU & ran 8 jts, 8 5/8" 24# K-55 ST&C, set @ 350'. Cement w/225 sks Class "C" w/2% CaCl₂. Plug down 11:40A, 1-14-82. Waiting on cement 18 hrs. Circ cement to surface. Test casing to 1000#. Drill float & cement.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Area Drlg. Superintendent DATE 1-21-82
Orig. Signed by
Jerry Sexton
APPROVED BY Dick L. Sager TITLE _____ DATE JAN 22 1982
CONDITIONS OF APPROVAL, IF ANY: